

FIELD REPAIR PACKS FOR HDT BASE-X® FAMILY OF SHELTERS



HDT Fully Mission Capable Packs are a convenient way to order common replacement parts for HDT Base-X® shelters. HDT repair packs include items that are commonly misplaced or worn over time and help return your Base-X shelter to full mission capability.

BASE-X® 100 SERIES FIELD REPAIR PACK

This replacement parts pack includes scissors, leg assemblies, hardware, hubs, repair adhesive, tools and a zippered carrying bag.

BASE-X® 200 SERIES FIELD REPAIR PACK

This replacement parts pack includes scissors, leg assemblies, hardware, hubs, repair adhesive, tools and a zippered carrying bag.

BASE-X® 300 & 500 SERIES FIELD REPAIR PACK

This replacement parts pack includes scissors, leg assemblies, hardware, hubs, repair adhesive, tools and a zippered carrying bag.

BASE-X® 6D31 SERIES FIELD REPAIR PACK

This replacement parts pack includes scissors, leg assemblies, hardware, hubs, repair adhesive, tools and a zippered carrying bag.

BASE-X® 8D36 SERIES FIELD REPAIR PACK

This replacement parts pack includes scissors, leg assemblies, hardware, hubs, repair adhesive, tools and a zippered carrying bag.

AFTERMARKET SUPPORT FOR:



Base-X® 100 Series



Base-X® 200 Series



Base-X® 300 & 500 Series



Base-X® 6D31 Series



Base-X® 8D36 Series

FIELD REPAIR PACKS FOR HDT BASE-X® FAMILY OF SHELTERS



Base-X® 100 Shelter Series Field Repair Pack		
Description	Part Number	Quantity
Repair Pack Bag	65901BK	1
Split Ring Pliers	48-SPLTRNG-01	1
7/16" Open End 12-PT Box Wrench	48-BW716-01	1
Hub Lock Assembly	65001	1
180° Scissor Assembly	65061A	1
90° Scissor Assembly	65091A	1
Leg Assembly	65300100	1
Clevis Pin 3/16" x 1 1/2"	69CP3010	5
Clevis Pin 3/16" x 1 3/4"	69CP3020	4
Clevis Pin 3/16" x 2 1/2"	69CP301025	2
Plastic Disk	69DP01	1
Liner Clip Assembly	69LCA	1
Split Ring	69SR040	10
Cotter Pin 3/32" x 1/2"	69SR041	7
Rubber Washer	69WR006	3
Hex Head Screw, 1/4–20" x 1"	HHHC06BLK	3
Hex Head Screw, 1/4–20" x 3/4"	HHHC04BLK	1
Fender Washer 1 1/4"	HRWBLK	3
Adhesive Back Fabric – Outer (Green)	FV44103ADHFG	1
Adhesive Back Fabric – Outer (Tan)	FV44103ADHTN	1
Adhesive Back Fabric – Liner	H017681	1

Base-X® 200 Shelter Series Field Repair Pack		
Description	Part Number	Quantity
Repair Pack Bag	65901BK	1
Split Ring Pliers	48-SPLTRNG-01	1
7/16" Open End 12-PT Box Wrench	48-BW716-01	1
Hub Lock Assembly	65001	1
45° Scissor Assembly	65051A	3
180° Scissor Assembly	65061A	3
Leg Assembly	65300100	1
Clevis Pin 3/16" x 1 1/2"	69CP3010	5
Clevis Pin 3/16" x 1 3/4"	69CP3020	4
Plastic Disk	69DP01	1
Liner Clip Assembly	69LCA	1
Split Ring	69SR040	10
3/32" x 1/2" Cotter Pin	69SR041	7
Rubber Washer	69WR006	3
Hex Head Screw, 1/4–20" x 1"	HHHC06BLK	3
Hex Head Screw, 1/4–20" x 3/4"	HHHC04BLK	1
Fender Washer 1 1/4"	HRWBLK	3
Adhesive Back Fabric – Outer (Green)	FV44103ADHFG	1
Adhesive Back Fabric – Outer (Tan)	FV44103ADHTN	1
Adhesive Back Fabric – Liner	H017681	1

FIELD REPAIR PACKS FOR HDT BASE-X® FAMILY OF SHELTERS



Base-X® 300 & 500 Shelter Series Field Repair Pack		
Description	Part Number	Quantity
Repair Pack Bag	65901BK	1
Split Ring Pliers	48-SPLTRNG-01	1
7/16" Open End 12-PT Box Wrench	48-BW716-01	1
Hub Lock Assembly	65001	1
45° Scissor Assembly	65051A	3
180° Scissor Assembly	65061A	3
Leg Assembly	65300100	1
Clevis Pin 3/16" x 1 1/2"	69CP3010	5
Clevis Pin 3/16" x 1 3/4"	69CP3020	4
Clevis Pin 3/16" x 2 1/2"	69CP301025	4
Double Head Clevis Pin 3/16" x 1 1/2"	69CPDH3010	3
Plastic Disk	69DP01	1
Liner Clip Assembly	69LCA	1
Split Ring	69SR040	10
Cotter Pin 3/32" x 1/2"	69SR041	7
Rubber Washer	69WR006	3
Hex Head Screw, 1/4–20" x 1"	HHHC06BLK	3
Hex Head Screw, 1/4–20" x 3/4"	HHHC04BLK	1
Fender Washer 1 1/4"	HRWBLK	3
Adhesive Back Fabric – Outer (Green)	FV44103ADHFG	1
Adhesive Back Fabric – Outer (Tan)	FV44103ADHTN	1
Adhesive Back Fabric – Liner	H017681	1

Base-X® 6D31 Shelter Series Field Repair Pack		
Description	Part Number	Quantity
Repair Pack Bag	65901BK	1
Split Ring Pliers	48-SPLTRNG-01	1
7/16" Open End 12-PT Box Wrench	48-BW716-01	1
Hub Lock Assembly	65001	1
Hub Lock Assembly, Dome	65001D	1
45° Floating Scissor Strut	65051FLOAT	4
180° Scissor Assembly	65061A	3
Leg Assembly	65300100	1
Clevis Pin 3/16" x 1 1/2"	69CP3010	5
Clevis Pin 3/16" x 1 3/4"	69CP3020	4
O-Ring 1.2" x 1.5"	69OR001	5
Plastic Disk	69DP01	1
Liner Clip Assembly	69LCA	1
Split Ring	69SR040	10
Cotter Pin 3/32" x 1/2"	69SR041	7
Rubber Washer	69WR006	3
Hex Head Screw, 1/4–20" x 1"	HHHC06BLK	3
Hex Head Screw, 1/4–20" x 3/4"	HHHC04BLK	1
Fender Washer 1 1/4"	HRWBLK	3
Adhesive Back Fabric – Outer (Green)	FV44103ADHFG	1
Adhesive Back Fabric – Outer (Tan)	FV44103ADHTN	1
Adhesive Back Fabric – Liner	H017681	1

FIELD REPAIR PACKS FOR HDT BASE-X® FAMILY OF SHELTERS



Base-X® 8D36 Shelter Series Field Repair Pack		
Description	Part Number	Quantity
Repair Pack Bag	65901BK	1
Split Ring Pliers	48-SPLTRNG-01	1
7/16" Open End 12-PT Box Wrench	48-BW716-01	1
Hub Lock Assembly	65001	1
Hub Lock Assembly, Dome	65001D	1
49" Floating Scissor Strut	61049FLOAT	2
45° Floating Scissor Strut	61051FLOAT	4
180° Scissor Assembly	65061A	3
Leg Assembly	65300100	1
Clevis Pin 3/16" x 1 1/2"	69CP3010	5
Clevis Pin 3/16" x 1 3/4"	69CP3020	4
O-Ring 1.2" x 1.5"	69OR001	5
Plastic Disk	69DP01	1
Liner Clip Assembly	69LCA	1
Split Ring	69SR040	10
Cotter Pin 3/32" x 1/2"	69SR041	7
Rubber Washer	69WR006	3
Hex Head Screw, 1/4-20" x 1"	HHHC06BLK	3
Hex Head Screw, 1/4-20" x 3/4"	HHHC04BLK	1
Fender Washer 1 1/4"	HRWBLK	3
Adhesive Back Fabric – Outer (Green)	FV44103ADHFG	1
Adhesive Back Fabric – Outer (Tan)	FV44103ADHTN	1
Adhesive Back Fabric – Liner	H017681	1

HDT Expeditionary Systems, Inc.

30500 Aurora Road, Suite 100, Solon, OH 44139 USA

P 800.969.8527 / 216.HDT.6111 / www.hdtglobal.com / sales@hdtglobal.com