

ENERGY EFFICIENCY SHELTERS

Insulated Liners for AirBeam® Shelters



The HDT Insulated Liner creates an insulated thermal barrier. This increased efficiency reduces the energy needed to heat or cool a shelter. Once it is installed, it can remain in place even during the shelter strike process.

HDT's insulated liner configuration provides a superior radiant / insulative barrier for conductive, convective and radiant heat transfer. The liner is ruggedized ensuring that it is puncture and tear resistant. In addition, the liner is flame resistant to industry standards and does not promote growth of fungi or bacteria.

KEY FEATURES

Up to 75% reduction in HVAC run time

- Insulated liner material does not absorb water
- Insulated liner material maintains shelter mobility
- Effective R Value of 6
- Shelters maintains wind and snow loading rating
- Tested and approved to ASTM D6413 Flame Resistance
- Mold and mildew resistant



ENERGY EFFICIENCY SHELTERS

Insulated Liners for AirBeam® Shelters



AIRBEAM AMEDD SHELTER SYSTEMS WITH INSULATED LINERS

	2016	2021	2032	2064 MED	2064 SUR
HDT Part Number					
Olive Drab	102-H041306-120	102-H041307-120	102-H041308-120	102-H041309-120	102-H041310-120
Tan	102-H041306-130	102-H041307-130	102-H041308-130	102-H041309-130	102-H041310-130

AIRBEAM AMEDD INSULATED LINER PACKAGES

	2016	2021	2032	2064
HDT Part Number	105-H030673	105-H030672	105-H030456	105-H030671
	ISO to Temper Passageway	ISO to ISO Passageway	Open End Boot	Temper Vestibule
HDT Part Number	104-H035778	104-H035776	105-H030674	104-H030675

AIRBEAM TOC SHELTER ASSEMBLIES WITH INSULATED LINERS

	2011A	2021D	2032B	2032C
HDT Part Number				
Olive Drab	102-H039374-120	102-H039375-120	102-H039376-120	102-H039377-120
Tan	102-H039374-130	102-H039375-130	102-H039376-130	102-H039377-130

AIRBEAM TOC SHELTER ASSEMBLY INSULATED LINER PACKAGES

	2011A	2021D	2032B	2032C	Temper Vestibule
HDT Part Number	105-H039383	105-H032757	105-H032758	105-H039385	104-H030675

Products, product specifications and data are subject to change without notice to improve reliability, function, and/or design.

Please contact Customer Service at 800.969.8527 for the most up-to-date product information.

NON-EXPORT CONTROLLED INFORMATION

HDT Expeditionary Systems, Inc.

30500 Aurora Road, Suite 100, Solon, OH 44139 USA

P 800.969.8527 / 216.HDT.6111 / sales@hdtglobal.com

Revision 2 09-25 01-02-01-0566